

Author's Accepted Manuscript

Surface crack formation on rails at grinding induced martensite white etching layers

Carsten Jørn Rasmussen, Søren Fæster, Somrita Dhar, Jesper Viggo Quaade, Manuel Bini, Hilmar Kjartansson Danielsen



PII: S0043-1648(17)30286-7
DOI: <http://dx.doi.org/10.1016/j.wear.2017.04.014>
Reference: WEA102143

To appear in: *Wear*

Received date: 3 February 2017
Revised date: 31 March 2017
Accepted date: 21 April 2017

Cite this article as: Carsten Jørn Rasmussen, Søren Fæster, Somrita Dhar, Jesper Viggo Quaade, Manuel Bini and Hilmar Kjartansson Danielsen, Surface crack formation on rails at grinding induced martensite white etching layers, *Wear* <http://dx.doi.org/10.1016/j.wear.2017.04.014>

This is a PDF file of an unedited manuscript that has been accepted for publication. As a service to our customers we are providing this early version of the manuscript. The manuscript will undergo copyediting, typesetting, and a review of the resulting galley proof before it is published in its final citable form. Please note that during the production process errors may be discovered which could affect the content, and all legal disclaimers that apply to the journal pertain.

Surface crack formation on rails at grinding induced martensite white etching layers

Carsten Jørn Rasmussen¹, Søren Fæster², Somrita Dhar², Jesper Viggo Quaade², Manuel Bini², Hilmar Kjartansson Danielsen^{2*}

¹Banedanmark, Amerika Plads 15, 2100 København Ø, Denmark

²DTU Wind Energy, Frederiksborgvej 399, 4000 Roskilde, Denmark

*corresponding author, hkda@dtu.dk

Abstract

The connection between profile grinding of rails, martensite surface layers and crack initiation has been investigated using visual inspection, optical microscopy and 3D X-ray computerized tomography. Newly grinded rails were extracted and found to be covered by a continuous surface layer of martensite with varying thickness formed by the grinding process. Worn R350HT and R200 rails were extracted from the Danish rail network as they had transverse bands resembling grinding marks on the running surface. The transverse bands were shown to consist of martensite which had extensive crack formation at the martensite/pearlite interface. The cracks in R350HT propagated down into the rail while those in the soft R200 returned to the surface causing only very small shallow spallation. The transverse bands had the same shape, size, orientation, location and periodicity which would be expected from grinding marks, showing a clear connection between grinding and crack initiation.

Keywords: Grinding; Railway; Steel; Martensite

Abstract

The connection between profile grinding of rails, martensite surface layers and crack initiation has been investigated using visual inspection, optical microscopy and 3D X-ray computerized tomography. Newly grinded rails were extracted and found to be covered by a continuous surface layer of martensite with varying thickness formed by the grinding process. Worn R350HT and R200 rails were extracted from the Danish rail network as they had transverse bands resembling grinding marks on the running surface. The transverse bands were shown to consist of martensite which had extensive crack formation at the martensite/pearlite interface. The cracks in R350HT propagated down into the rail while those in the soft R200 returned to the surface causing only very small shallow spallation. The transverse bands had the same shape, size, orientation, location and periodicity which would be expected from grinding marks, showing a clear connection between grinding and crack initiation.

Download English Version:

<https://daneshyari.com/en/article/4986459>

Download Persian Version:

<https://daneshyari.com/article/4986459>

[Daneshyari.com](https://daneshyari.com)