


Accepted Manuscript

Failure analysis of elbow pipe cracking in a residual heat-removal system of a nuclear power plant

Yin Kaiju, Tang Wu, Zhang Min, Xiao Jun, Zhang Qiang, Xu Qi, Tang Rui, Qiu Shaoyu, Chen Yong



PII: S1350-6307(17)30269-8
DOI: doi: [10.1016/j.engfailanal.2017.08.019](https://doi.org/10.1016/j.engfailanal.2017.08.019)
Reference: EFA 3273
To appear in: *Engineering Failure Analysis*
Received date: 17 March 2017
Revised date: 4 August 2017
Accepted date: 28 August 2017

Please cite this article as: Yin Kaiju, Tang Wu, Zhang Min, Xiao Jun, Zhang Qiang, Xu Qi, Tang Rui, Qiu Shaoyu, Chen Yong , Failure analysis of elbow pipe cracking in a residual heat-removal system of a nuclear power plant, *Engineering Failure Analysis* (2017), doi: [10.1016/j.engfailanal.2017.08.019](https://doi.org/10.1016/j.engfailanal.2017.08.019)

This is a PDF file of an unedited manuscript that has been accepted for publication. As a service to our customers we are providing this early version of the manuscript. The manuscript will undergo copyediting, typesetting, and review of the resulting proof before it is published in its final form. Please note that during the production process errors may be discovered which could affect the content, and all legal disclaimers that apply to the journal pertain.

Failure analysis of elbow pipe cracking in a residual heat-removal system of a nuclear power plant

Yin Kaiju^{1,2}, Tang Wu¹, zhang Min³, Xiao Jun², Zhang Qiang², Xu Qi², Tang Rui²,
Qiu Shaoyu², Chen Yong²

(1. State Key Laboratory of Electronic Thin Films and Integrated Devices, University of Electronic Science and Technology of China, Chengdu 610054, P. R. China)

(2. Laboratory of Science and Technology on Reactor Fuel and Materials, Nuclear Power Institute of China, Chengdu 610041, P. R. China)

(3. Daya Bay Nuclear Power Plant, Shenzhen 518124, P. R. China)

Abstract: Failure analysis of an elbow pipe in a nuclear power plant is conducted through non-destructive tests, chemical composition analysis, mechanical property tests, scanning electronic microscopy of fracture morphology, energy spectrum and micro-structure analyses, and cold-work elongation analysis. Results reveal the presence of many cold-worked slip bands in the micro-structures. The cold-work elongation is about 32% in the crack regime, the hardness is 390 HV_{0.1}, the crack presents embrittlement and propagates along the grain boundary, and the fracture presents crystal characteristics. The failure mode of the pipe is inter-granular stress corrosion crack, and the main reason for this failure is the high-cold-worked condition.

Keywords: elbow pipe failure, crack propagation, cold work hardening, IGSCC

1 Introduction

A leakage was discovered on an elbow pipe of a residual heat-removal system in a nuclear power plant (NPP) located in south China in October 2010. In situ ultrasonic and radiographic inspections revealed through-wall cracking in the elbow. The State Bureau of Nuclear Safety classified this event as class 1 according to the classification criteria for international nuclear events established by the International Atomic Energy Association.

The failure elbow was made of 316LN with a size of 355.6 mm × 40 mm. The coolant does not flow in this section during normal operations of the power plant. After in situ inspection, the elbow was cut from the pipe and sent to a laboratory for further investigation. The failure mode and mechanism were determined through various

Download English Version:

<https://daneshyari.com/en/article/7167635>

Download Persian Version:

<https://daneshyari.com/article/7167635>

[Daneshyari.com](https://daneshyari.com)