

Accepted Manuscript


Oil well drill bit failure during pull out: Redesign to reduce its consequences

P. Cirimello, J.L. Otegui, J. Martinez Sanchez, G. Carfi

PII: S1350-6307(16)30839-1
DOI: [doi:10.1016/j.engfailanal.2017.09.020](https://doi.org/10.1016/j.engfailanal.2017.09.020)
Reference: EFA 3303
To appear in: *Engineering Failure Analysis*
Received date: 27 September 2016
Accepted date: 30 September 2017

Please cite this article as: P. Cirimello, J.L. Otegui, J. Martinez Sanchez, G. Carfi , Oil well drill bit failure during pull out: Redesign to reduce its consequences. The address for the corresponding author was captured as affiliation for all authors. Please check if appropriate. Efa(2017), doi:[10.1016/j.engfailanal.2017.09.020](https://doi.org/10.1016/j.engfailanal.2017.09.020)

This is a PDF file of an unedited manuscript that has been accepted for publication. As a service to our customers we are providing this early version of the manuscript. The manuscript will undergo copyediting, typesetting, and review of the resulting proof before it is published in its final form. Please note that during the production process errors may be discovered which could affect the content, and all legal disclaimers that apply to the journal pertain.



Oil Well drill bit failure during pull out: redesign to reduce its consequences.

P. Cirimello¹, J. L. Otegui^{1,2}; J. Martinez Sanchez³; G. Carfi¹,

¹YPF Tecnología S.A, Argentina; ² CONICET, Argentina; ³INVAP Ingeniería S.A

pablo.g.cirimello@ypftecnologia.com

Abstract:

A drill bit with polycrystalline diamond (PDC) inserts lost one of its three blades when operating in an oil well, leading to a costly failure. Operating conditions and associated stresses were analyzed, bit core material in the failure and adjacent areas was analyzed and tested, and fracture surfaces identified.

Base material is a Ni-Cu-Mn matrix with tungsten carbide precipitates. Fracture surfaces showed cleavage planes and loss of particles, indicating a brittle fracture. Microstructures and hardness were similar in all analyzed regions, and according to specifications.

The symmetry and characteristics of the fracture surfaces allow defining that the loads that caused the failure were not applied during the drilling operation. The blade broke apart due to a downward force applied at its base. Finite elements numerical modeling allowed pinpointing a specific moment in the pulling operation, in which a 28 ton overpull force was recorded, as the immediate operational event that caused the failure.

Operating procedures that reduce the likelihood and amplitude of impact loads, are difficult to implement; more promising is the alternative for a redesign of the drill bit. Commercial designs focus mostly on the efficiency of the cutting cycle; blade geometry can be also optimized to take into account the pull out conditions. The most efficient redesign for this specific drill bit model relies in a re-machining of the blade base, so that a large overpull load would crack a small sector, on which a PDC insert is located. In this gecko-tail type solution, only one insert would be lost, preserving the integrity of the rest of the drill-bit. Subsequent repair would involve standard thermal spray base metal techniques, including reconstitution and brazing of a new insert.

Key words: Drill bit; PDC; impact loads; redesign

Download English Version:

<https://daneshyari.com/en/article/7167732>

Download Persian Version:

<https://daneshyari.com/article/7167732>

[Daneshyari.com](https://daneshyari.com)