



11th Nordic Symposium on Building Physics, NSB2017, 11-14 June 2017, Trondheim, Norway

Long term monitoring of repaired external wall assembly

Susanna Ahola^{a*}, Jukka Lahdensivu^b

^aRamboll Finland Oy, P.O. Box 718 FI-33101 Tampere, Finland

^bTampere University of Technology, P.O. Box 600 FI-33101 Tampere, Finland

Abstract

This study discusses on hygrothermal performance of external wall assembly based on long term observation on relative humidity and temperature in layered external wall assembly, when the resistance of water vapor in insulating material is higher than in the main framing of the studied building. In this case the location of the vapor barrier must be examined more closely.

In 1974 completed building the facade of the building was made from concrete and bricks. The external wall assembly was repaired by replacing the thermal insulation and facade brickwork. The original brick-insulation-brick structure was unventilated like those used to be until mid-1980s. The repaired outer layer was constructed with a ventilation gap which satisfies the building codes in force. Old thermal insulation was replaced with aluminum foil backed polyurethane insulation. The aim of the study was to verify that the new structure was performing properly by measuring the circumstances inside the new external wall assembly. The performance of the repaired external wall was monitored by sensors installed in four depths and in five different locations in the building. Each of the sensors measured relative humidity and temperature for two years.

The repaired external wall assembly was observed to be performing correctly. The aluminum foil backed polyurethane insulation functioned as planned as wall assembly's thermal insulation and vapor barrier. Condensation of the indoor air into the structure was not detected during the measurement period. Neither was the outside air's relative humidity condensed outside the vapor barrier during the measurement period. There was no observation of the condensation neither in the ventilation gap, nor in the fire resistant mineral wool layer during the measurement period, in any inside or outside circumstances.

© 2017 The Authors. Published by Elsevier Ltd.

Peer-review under responsibility of the organizing committee of the 11th Nordic Symposium on Building Physics.

Keywords: Brick-insulation-brick structure; monitoring; relative humidity; condensation; diffusion

* Corresponding author. Tel.: +358 40 5163028
E-mail address: susanna.ahola@ramboll.fi

1. Introduction

The study discusses on hygrothermal performance of external wall assembly in listed educational building situated in mid-Finland. The building was completed in 1974 and completely renovated in 2012. This study concentrates on both repairation of the original brick-mineral wool-brick external wall assembly, and monitoring the on the success of the repairation. Structures of wall assemblies are shown in Figs. 1 and 2.




Fig. 1 The original external wall assembly




Fig. 2 The repaired external wall assembly

1.1 Moisture sources of external wall assembly

Common sources of moisture in walls are air leakage in vapor barrier and accidental water leakage. In addition, the following sources were identified critical in this study:

Wind driven rain

The most important moisture source for external wall assembly is wind driven rain. The higher building, the more wind driven rain facades will get [1]. In Finland wind driven rain comes with south-west to south-east winds. Roughly it could be stated that in coastal areas of Finland 60 % of wind driven rain hits to facades while the share in inland is only 40 %. The difference is based on the higher wind speed during rain events in coastal area than inland [2]. The average wind speed during rain event in coastal area is 8 m/s and in inland 4 m/s. The amount of rain in coastal area is approximately 600 mm/a, and in inland app. 450 mm/a. [3]. Together with higher wind speed during rain events, facades in coastal area gets a lot more wet than in inland.

Brick is porous material and its capillary wetting receptivity and receptivity speed are high. Relatively thin brickwork could be totally saturated during rain.

Convection

In well performing ventilated wall structures convection is not normally an issue. But because of bad labor work, ventilation gap might be too narrow and mortar has a contact to inner wall structures. This phenomenon has been detected in several cases. Moisture from wet brickwork could connect to thermal insulation and other parts of wall assembly if mortar is connected to the thermal insulation in some parts of the wall assembly.

However, both wind driven rain and convection should not be an issue after the external wall assembly has been renovated, but they had very important role in degradation of the original one.

Diffusion

Moisture content difference in pore structure of material or in the air tends to stabilize during the time. Moisture tend to move due diffusion to lover moisture content, which means, that the direction of moisture flow will change according to moisture level of studied material. In external wall assembly this means moisture flow from outside to inside during rain events in summer time and from inside to outside during cold season.

In the cavity wall, where the outer layer consists of brickwork, saturated brickwork keeps the relative humidity of air in the ventilation gap relatively high during several hours after rain has been stopped. The air change rate on the ventilation gap depends strongly on windiness and temperature difference between ventilation gap and outdoor air. Usually air change rate is very small

Download English Version:

<https://daneshyari.com/en/article/7919319>

Download Persian Version:

<https://daneshyari.com/article/7919319>

[Daneshyari.com](https://daneshyari.com)