Accepted Manuscript

Microscopical observations of inter-fibre failure under tension

Elena Correa, María Inmaculada Valverde, María Luisa Velasco, Federico París

PII: S0266-3538(17)32323-0

DOI: 10.1016/j.compscitech.2017.12.009

Reference: CSTE 6997

To appear in: Composites Science and Technology

Received Date: 16 September 2017

Revised Date: 8 December 2017

Accepted Date: 8 December 2017

Please cite this article as: Correa E, Valverde MaríInmaculada, Velasco MaríLuisa, París F, Microscopical observations of inter-fibre failure under tension, *Composites Science and Technology* (2018), doi: 10.1016/j.compscitech.2017.12.009.

This is a PDF file of an unedited manuscript that has been accepted for publication. As a service to our customers we are providing this early version of the manuscript. The manuscript will undergo copyediting, typesetting, and review of the resulting proof before it is published in its final form. Please note that during the production process errors may be discovered which could affect the content, and all legal disclaimers that apply to the journal pertain.



ACCEPTED MANUSCRIPT

Microscopical observations of inter-fibre failure under tension Elena Correa*, María Inmaculada Valverde, María Luisa Velasco, Federico París Departamento de Mecánica de Medios Continuos y Teoría de Estructuras, Grupo de Elasticidad y Resistencia de Materiales, Escuela Técnica Superior de Ingeniería, Universidad de Sevilla, Camino de los Descubrimientos s/n, 41092, Sevilla, España *Corresponding author <u>ecorrea@us.es</u> Abstract

The numerical study of the inter-fibre failure at micromechanical level predicts the appearance of different stages in the development of this damage mechanism; these studies have also allowed the main features of each stage (such as the interfacial debond length and the kinking angle) to be identified.

The development of experimental studies aiming to check the relevance of the aforementioned numerical results is crucial. Based on this, this research focused on the tensile test under different loading levels of specimens manufactured from carbon-epoxy cross-ply symmetrical laminates. The microscopic observation of the 90° layers leads to the analysis of the appearance of the transverse cracks as a function of the load, the identification of the previously numerically predicted stages of the mechanism of damage, the measurement of key parameters and the evaluation of the influence of nearby fibres. A clear connection between the numerical and experimental results has been found.

Keywords: B. debonding; C. transverse cracking; D. optical microscopy; cross-ply

1. Introduction

Matrix/Inter-fibre failure arises in plies subjected to transverse loads, being characteristic, among others, of 90° plies belonging to cross-ply laminates subjected to loads parallel to their 0° plies.

Previous numerical studies allowed the identification of three main stages in the

Download English Version:

https://daneshyari.com/en/article/7214891

Download Persian Version:

https://daneshyari.com/article/7214891

Daneshyari.com