


## Accepted Manuscript

Title: High Resolution Characterization of Sulfur-Assisted Degradation in Alloy 800

Authors: S.Y. Persaud, F. Long, A. Korinek, J.M. Smith

PII: S0010-938X(18)30261-0  
DOI: <https://doi.org/10.1016/j.corsci.2018.06.010>  
Reference: CS 7566



To appear in:

Received date: 7-2-2018  
Revised date: 6-6-2018  
Accepted date: 8-6-2018

Please cite this article as: Persaud SY, Long F, Korinek A, Smith JM, High Resolution Characterization of Sulfur-Assisted Degradation in Alloy 800, *Corrosion Science* (2018), <https://doi.org/10.1016/j.corsci.2018.06.010>

This is a PDF file of an unedited manuscript that has been accepted for publication. As a service to our customers we are providing this early version of the manuscript. The manuscript will undergo copyediting, typesetting, and review of the resulting proof before it is published in its final form. Please note that during the production process errors may be discovered which could affect the content, and all legal disclaimers that apply to the journal pertain.

## High Resolution Characterization of Sulfur-Assisted Degradation in Alloy 800

S.Y. Persaud<sup>1,2</sup>, F. Long<sup>1</sup>, A. Korinek<sup>3</sup>, and J.M. Smith<sup>2</sup>

<sup>1</sup>Department of Mechanical and Materials Engineering, Queen's University, Nicol Hall, 60 Union Street W, Kingston, ON, K7L 2N8

<sup>2</sup>Canadian Nuclear Laboratories, 286 Plant Road, Chalk River, ON, K0J 1J0, Canada

<sup>3</sup>Canadian Centre for Electron Microscopy (CCEM), McMaster University, 1280 Main Street West, Hamilton, ON, L8S 4M1, Canada

Corresponding authors, E-mail addresses: suraj.persaud@queensu.ca (S.Y. Persaud), jared.smith@cnl.ca (J.M. Smith), Tel.: +1613-533-6000 ext. 74015.

### Highlights

- EAC, IGC, and pitting occurred in Alloy 800 exposed to a 280 °C acid-sulfate environment.
- Nano-scale chemical characterization at crack tips revealed mixed Ti- and Cr-rich oxide(s) with sulfur incorporated.
- Adsorption of sulfur leads to a poorly adherent mixed oxide/sulfide layer, propagating EAC via film-rupture.
- Nano-scale characterization of pits revealed a 10 nm thick sulfur layer and minimal oxides.
- Transition from EAC to pitting occurs at near-complete sulfur surface coverage, which limits oxide nucleation.

### Abstract

Environmentally assisted cracking (EAC) initiation tests were carried out by subjecting Alloy 800 tensile specimens to 0.55 mol/kg  $\text{SO}_4^{2-}$  solution,  $\text{pH}_{280^\circ\text{C}}$  3, at 280 °C using slow rise-time cyclic loading and in-situ crack detection. EAC, intergranular corrosion (IGC), and pitting were observed. Transmission electron microscopy analysis revealed Ti- and Cr-rich oxides in cracks, and sulfur incorporated in oxide(s) or as sulfide compound(s). This oxide/sulfide film is likely impaired, producing a slip dissolution-type EAC mechanism. For pitting, only a nano-scale sulfur

Download English Version:

<https://daneshyari.com/en/article/7893196>

Download Persian Version:

<https://daneshyari.com/article/7893196>

[Daneshyari.com](https://daneshyari.com)