

Gold deposition caused by carbonation of biotite during late-stage fluid flow

Mark A. Pearce, Alistair J.R. White, Louise A. Fisher, Robert M. Hough, James S. Cleverley

PII: S0024-4937(15)00371-0
DOI: doi: 10.1016/j.lithos.2015.10.010
Reference: LITHOS 3721

To appear in: *LITHOS*

Received date: 20 May 2015
Accepted date: 20 October 2015

Please cite this article as: Pearce, Mark A., White, Alistair J.R., Fisher, Louise A., Hough, Robert M., Cleverley, James S., Gold deposition caused by carbonation of biotite during late-stage fluid flow, *LITHOS* (2015), doi: 10.1016/j.lithos.2015.10.010

Gold deposition caused by carbonation of biotite during late-stage fluid flow

Mark A. Pearce[1]*, Alistair J.R. White[1], Louise A. Fisher[1], Robert M. Hough[1], James S. Cleverley[1,2]

[1]CSIRO Mineral Resources, Australian Resources Research Centre, 26 Dick Perry Avenue, Kensington, WA 6151, Australia

[2]Current Address: Reflex, 216 Balcatta Road, Balcatta, WA 6021, Australia

*Corresponding Author; mark.pearce@csiro.au

Keywords: gold mineralization; fluid-rock reaction; microstructure; thermodynamic modelling