


## Accepted Manuscript

Failure of bolt support and experimental study on the parameters of bolt-grouting for supporting the roadways in deep coal seam

R. Pan, Q. Wang, B. Jiang, S.C. Li, H.B. Sun, Q. Qin, H.C. Yu, W. Lu



PII: S1350-6307(16)31115-3  
DOI: doi: [10.1016/j.engfailanal.2017.06.025](https://doi.org/10.1016/j.engfailanal.2017.06.025)  
Reference: EFA 3190  
To appear in: *Engineering Failure Analysis*  
Received date: 17 November 2016  
Revised date: 6 June 2017  
Accepted date: 14 June 2017

Please cite this article as: R. Pan, Q. Wang, B. Jiang, S.C. Li, H.B. Sun, Q. Qin, H.C. Yu, W. Lu, Failure of bolt support and experimental study on the parameters of bolt-grouting for supporting the roadways in deep coal seam, *Engineering Failure Analysis* (2017), doi: [10.1016/j.engfailanal.2017.06.025](https://doi.org/10.1016/j.engfailanal.2017.06.025)

This is a PDF file of an unedited manuscript that has been accepted for publication. As a service to our customers we are providing this early version of the manuscript. The manuscript will undergo copyediting, typesetting, and review of the resulting proof before it is published in its final form. Please note that during the production process errors may be discovered which could affect the content, and all legal disclaimers that apply to the journal pertain.

Failure of bolt support and experimental study on the parameters of bolt-grouting  
for supporting the roadways in deep coal seam

R. Pan<sup>a,b</sup>, Q. Wang<sup>a,b,c,\*</sup>, B. Jiang<sup>a,d</sup>, S.C. Li<sup>a</sup>, H.B. Sun<sup>a</sup>, Q. Qin<sup>a</sup>, H.C. Yu<sup>a</sup>, W. Lu<sup>a</sup>

*a Research Center of Geotechnical and Structural Engineering, Shandong University, Jinan 250061, China;*

*b Key Laboratory of Safety and High-efficiency Coal Mining, Ministry of Education (Anhui University of Science and Technology), Huainan, 232001, China;*

*c Key Laboratory for Geomechanics and Deep Underground Engineering, China University of Mining & Technology (Beijing), Beijing 100083, China;*

*d School of Civil Engineering and Architecture, University of Jinan, Jinan 250022, China*

Download English Version:

<https://daneshyari.com/en/article/5013505>

Download Persian Version:

<https://daneshyari.com/article/5013505>

[Daneshyari.com](https://daneshyari.com)