

Accepted Manuscript

Degradation and recovery of graphene/polymer interfaces under cyclic mechanical loading

Guorui Wang, Enlai Gao, Zhaohe Dai, Luqi Liu, Zhiping Xu, Zhong Zhang



PII: S0266-3538(17)30829-1

DOI: [10.1016/j.compscitech.2017.06.004](https://doi.org/10.1016/j.compscitech.2017.06.004)

Reference: CSTE 6799

To appear in: *Composites Science and Technology*

Received Date: 7 April 2017

Revised Date: 6 June 2017

Accepted Date: 8 June 2017

Please cite this article as: Wang G, Gao E, Dai Z, Liu L, Xu Z, Zhang Z, Degradation and recovery of graphene/polymer interfaces under cyclic mechanical loading, *Composites Science and Technology* (2017), doi: 10.1016/j.compscitech.2017.06.004.

This is a PDF file of an unedited manuscript that has been accepted for publication. As a service to our customers we are providing this early version of the manuscript. The manuscript will undergo copyediting, typesetting, and review of the resulting proof before it is published in its final form. Please note that during the production process errors may be discovered which could affect the content, and all legal disclaimers that apply to the journal pertain.

Degradation and Recovery of Graphene/Polymer Interfaces under Cyclic Mechanical Loading

Guorui Wang^{1,2}, *Enlai Gao*³, *Zhaohu Dai*², *Luqi Liu*^{2,*}, *Zhiping Xu*^{3,*}, *Zhong
Zhang*^{2,*}

¹ CAS Key Laboratory of Mechanical Behavior and Design of Materials, Department
of Modern Mechanics, University of Science and Technology of China, Hefei 230027,
China

² CAS Key Laboratory for Nanosystem and Hierarchical Fabrication, National Center
for Nanoscience and Technology, Beijing 100190, China

³ Applied Mechanics Laboratory, Department of Engineering Mechanics and Center
for Nano and Micro Mechanics, Tsinghua University, Beijing 100084, China

*Email: zhong.zhang@nanocr.cn, liulq@nanocr.cn, xuzp@tsinghua.edu.cn

Abstract: Interface failure is a common phenomenon for conventional composite materials when subjected to repeated mechanical loads, and it tends to be critical for nanocomposites due to several orders of magnitude enhancement in interfacial area. Herein, the graphene/poly(methyl methacrylate) (PMMA) interface when subjected to cyclic loading conditions exhibits obvious mechanical degradation through interfacial

Download English Version:

<https://daneshyari.com/en/article/5022054>

Download Persian Version:

<https://daneshyari.com/article/5022054>

[Daneshyari.com](https://daneshyari.com)