Accepted Manuscript

One dimensional equivalent linear ground response analysis — A case study of collapsed Margalla Tower in Islamabad during 2005 Muzaffarabad Earthquake

K. Mahmood, Z. Rehman, K. Farooq, S.A. Memon

PII: DOI: Reference: S0926-9851(16)30114-8 doi: 10.1016/j.jappgeo.2016.04.015 APPGEO 2980

To appear in: Journal of Applied Geophysics

Received date:1 January 2015Revised date:19 April 2016Accepted date:23 April 2016



Please cite this article as: Mahmood, K., Rehman, Z., Farooq, K., Memon, S.A., One dimensional equivalent linear ground response analysis — A case study of collapsed Margalla Tower in Islamabad during 2005 Muzaffarabad Earthquake, *Journal of Applied Geophysics* (2016), doi: 10.1016/j.jappgeo.2016.04.015

This is a PDF file of an unedited manuscript that has been accepted for publication. As a service to our customers we are providing this early version of the manuscript. The manuscript will undergo copyediting, typesetting, and review of the resulting proof before it is published in its final form. Please note that during the production process errors may be discovered which could affect the content, and all legal disclaimers that apply to the journal pertain.

One Dimensional Equivalent Linear Ground Response Analysis- A Case Study of Collapsed Margalla Tower in Islamabad During 2005 Muzafarabad Earthquake

K. Mahmood¹, Z. Rehman^{2*}, K. Farooq³, S.A. Memon⁴

¹Assistant Professor, Department of Civil Engineering Sarhad University of Information Technology, Peshawar
²Lecturer, Department of Civil Engineering, UCET, UOS, Sargodha, Pakistan
³Professor, Department of Civil Engineering, University of Engineering & Technology, Lahore Pakistan
⁴Department of Civil Engineering COMSATS, Abbottabad, Pakistan

Details of Corresponding Author Zia-ur-Rehman² Email:engr_ziaurrehman@yahoo.com, engr.zrehman@gmail.com,

ABSTRACT

One dimensional equivalent linear ground response analysis was conducted in the Margalla Tower building in Islamabad, which collapsed during 2005 Muzzafarabad Earthquake. The analyses were conducted in DEEPSOIL software, without considering the effect of ground water table. The input subsoil data were selected from laboratory and field tests conducted for the site with bedrock at a depth of 21m as per site condition. The field and laboratory testing data showed that the subsoil beneath the Tower site was silty clay to lean clay according to the unified soil classification system. Four different accelerograms with PGA values of 0.17g, 0.15g, 0.22g and 0.21g, compatible with the earthquake in the target area were applied at the bedrock. The surface response spectra showed that, except the Accelerogram-1 all other three were amplified near the fundamental period of the site. The analyses showed that different PGA values (0.26g, 0.21g, 0.36g and 0.21g) were produced at the surface which can be explained due to the difference in the Fourier amplitude of input accelerograms. Furthermore, the different input accelerograms produced a different shear strain and thus mobilized different shear strength along the soil profile depth. Finally, the calculated response spectra of accelerograms were compared with the response spectra of Islamabad. The calculated spectral acceleration values were found to be higher than reported by the Building Code of Pakistan (0.16g to 0.24g).

Keywords: Ground response analysis; Geotechnical investigation; Fourier amplitude

spectrum; Response spectrum

Download English Version:

https://daneshyari.com/en/article/6446959

Download Persian Version:

https://daneshyari.com/article/6446959

Daneshyari.com