

Accepted Manuscript


Evaluation of hydrogen damage in a fire tube using microstructure/mechanical properties studies

R. Bakhtiari, Sh. Zangeneh

PII: S1350-6307(17)31020-8
DOI: [doi:10.1016/j.engfailanal.2018.03.030](https://doi.org/10.1016/j.engfailanal.2018.03.030)
Reference: EFA 3424
To appear in: *Engineering Failure Analysis*
Received date: 25 August 2017
Revised date: 17 March 2018
Accepted date: 19 March 2018

Please cite this article as: R. Bakhtiari, Sh. Zangeneh , Evaluation of hydrogen damage in a fire tube using microstructure/mechanical properties studies. The address for the corresponding author was captured as affiliation for all authors. Please check if appropriate. Efa(2018), doi:[10.1016/j.engfailanal.2018.03.030](https://doi.org/10.1016/j.engfailanal.2018.03.030)

This is a PDF file of an unedited manuscript that has been accepted for publication. As a service to our customers we are providing this early version of the manuscript. The manuscript will undergo copyediting, typesetting, and review of the resulting proof before it is published in its final form. Please note that during the production process errors may be discovered which could affect the content, and all legal disclaimers that apply to the journal pertain.



**Evaluation of hydrogen damage in a fire tube using
microstructure/mechanical properties studies**

R. Bakhtiari¹, Sh. Zangeneh¹

1-Department of Materials and Textile Engineering, Faculty of Engineering, Razi University, Kermanshah,
Iran.

Corresponding author: Tel.: +98 912 2720166; Fax: +98 8334283263
E-mail addresses: r.bakhtiari@razi.ac.ir

ACCEPTED MANUSCRIPT

Download English Version:

<https://daneshyari.com/en/article/7167321>

Download Persian Version:

<https://daneshyari.com/article/7167321>

[Daneshyari.com](https://daneshyari.com)